46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KT67NNV

Peugeot 3008 1.6 BlueHDi 120 Allure 5dr EAT6

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/01/2018	**Keys**	2	**CAP Clean**	£5,250.00
Year	2018	**Service history**	Yes	**CAP Average**	£4,550.00
Mileage	79,353 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£3,800.00
Fuel Type	DIESEL	**Number of stamps**	8	**Gearbox**	AUTOMATIC
Colour	GREY	**Last service date**	09/01/2026	**Gears**	6
VIN	VF3MCBHZWJS064589	**Last service miles**	69,852	**Doors**	5
Body Style	Hatchback	**MOT Due**	30/01/2027		

LAST SERVICE 09/01/2026 @ 69,852 MILES (8 SERVICES) Heating does not work
Intermittent hand brake fault

Tyres

NSF	NEXEN	6.0mm
NSR	DUNLOP	3.0mm
OSF	NEXEN	6.0mm
OSR	DUNLOP	3.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos

































Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osr
Chipped
1 To 5



3: Wheel osr
Corroded
Light



4: Door osr
Dented
2 Or Less UpTo 10mm



5: Wheel nsr
Corroded
Light




6: Door nsr
Dented
With Paint Damage



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Bumper Front
Chipped
1 To 5



9: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK