46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

OE19RNV

Peugeot 5008 1.6 PureTech 180 GT Line Premium 5dr EAT8

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	07/05/2019	**Body Style**	MPV	**Last service miles**	71,098
Year	2019	**Keys**	1	**MOT Due**	16/09/2027
Mileage	83,792 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	8
Colour	GREY	**Number of stamps**	5	**Doors**	5
VIN	VF3M45GFRKS193273	**Last service date**	09/09/2025		

LAST SERVICE 09/09/2025 @ 71,098 MILES (5 SERVICES)

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos




























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint




3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Dented
Between 10mm + 30mm



5: Door nsf
Chipped
1 To 5



6: Door nsr
Chipped
1 To 5



7: Door nsr
Chipped
Edge Chip



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




9: Wheel nsr
Scratched
Up To 50mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Door nsr
Dented
Between 10mm + 30mm



12: Boot Lid
Chipped
Edge Chip



13: Qtr Panel osr
Dented
Between 10mm + 30mm



14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Dented
2 Or Less UpTo 10mm



16: Door osr
Chipped
1 To 5



17: Door osf
Chipped
1 To 5



18: Wing osf
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Chipped
Edge Chip



21: Roof
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		