46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

PE14YDX

MERCEDES-BENZ B CLASS B180 CDI Sport 5dr

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	29/05/2014	**Colour**	SILVER	**Gearbox**	MANUAL
Year	2014	**VIN**	WDD2462122J242134	**Gears**	6
Mileage	113,605 Miles Warranted	**Body Style**	MPV	**Doors**	5
		MOT Due	12/11/2026		
Fuel Type	DIESEL				

Tyres

NSF	BUDGET	Damaged
NSR	CONTINENTAL	Damaged
OSF	BUDGET	Damaged
OSR	CONTINENTAL	Damaged
Spare		


Photos



















Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
UpTo 25mm



2: Tyre osf
Damaged
Replace



3: Tyre nsf
Damaged
Replace



4: Tyre nsr
Damaged
Replace



5: Tyre osr
Damaged
Replace



6: Bonnet
Chipped
1 To 5



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Wheel nsf
Scratched
Over 50mm



10: Door nsf
Dented
2 Or Less UpTo 10mm



11: Door nsf
Chipped
Edge Chip



12: Door nsf
Chipped
1 To 5



13: Door nsr
Scratched
Over 25mm Thru Paint



14: Wheel nsr
Scratched
Over 50mm



15: Qtr Panel nsr
Dented
Over 30mm



16: Bumper Rear
Dented
Between 10mm + 30mm



17: Bumper Rear
Poor Previous Repair
Poor Paint




18: Boot Lid
Dented
With Paint Damage



19: Qtr Panel osr
Dented
With Paint Damage



20: C Post os
Dented
Over 30mm



21: Other
N/A
N/A
Roof rails scratched



22: Door osr
Dented
With Paint Damage



23: Wheel osr
Scratched
Over 50mm



24: Door osf
Chipped
Edge Chip



25: Wheel osf
Scratched
Over 50mm



26: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		