46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HV69OWD

Seat Arona 1.0 TSI 115 FR Sport [EZ] 5dr DSG

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/09/2019	**Body Style**	Hatchback	**Last service miles**	53,866
Year	2019	**Keys**	2	**MOT Due**	01/05/2027
Mileage	61,618 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	7
Colour	BLACK	**Number of stamps**	1	**Doors**	5
VIN	VSSZZZKJZLR024215	**Last service date**	10/10/2025		

Last Service - 10.10.25 @ 53866 miles (1 main dealer service)

Tyres

NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim


Photos










HV69 OWD





Please switch on dipped beam headlight





BAND
MENU
STATION LIST
Virgin Radio
VIEW
SETTINGS
MANUAL










Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Edge Chip



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Bonnet
Chipped
1 To 5



8: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK