46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YD64ZFK

Volvo XC60 D4 [181] SE 5dr AWD

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	27/09/2014	**Colour**	SILVER	**MOT Due**	30/10/2027
Year	2014	**VIN**	YV1DZ81A4F2670698	**Gearbox**	MANUAL
Mileage	150,920 Miles Warranted	**Body Style**	Estate	**Gears**	6
		Keys	1	**Doors**	5
Fuel Type	DIESEL				

Tyres

NSF	TRIANGLE	6.0mm
NSR	PIRELLI	2.0mm
OSF	TRIANGLE	6.0mm
OSR	PIRELLI	3.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear wiper
- Radio/CD
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Service indicator
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos

















Condition Check



Damage Photos




1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Dented
With Paint Damage



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Roof
Dented
Between 10mm + 30mm



10: Qtr Panel osr
Chipped
1 To 5



11: Wheel osr
Corroded
Light



12: Door osr
Dented
Between 10mm + 30mm



13: Door osr
Scratched
UpTo 25mm Thru Paint



14: Door osf
Dented
Between 10mm + 30mm



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK