46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HV66ZTJ

Kia Sportage 1.6 GDi ISG 2 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/10/2016	**Body Style**	Estate	**Last service miles**	72,169
Year	2016	**Keys**	2	**MOT Due**	30/10/2027
Mileage	91,685 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	7	**Doors**	5
VIN	U5YPH814LGL187474	**Last service date**	17/10/2023		

£100 ADDITIONAL FEE
Last Service - 17.10.2023 at 72169 miles (7 Services)
NSF door will not open from outside

Tyres

NSF	LAUFENN	5.0mm
NSR	FALKEN	5.0mm
OSF	LAUFENN	5.0mm
OSR	PIRELLI	6.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos



















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Broken
Replace



4: Bumper Front
Scratched
25 to 100mm Thru Paint




5: Wing nsf
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Chipped
Multiple Chips



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint




13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Poor Previous Repair
Rippled UpTo 30%



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Poor Previous Repair
Rippled UpTo 30%




17: Door osf
Scratched
Over 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK