46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GF20HXM**

## Vauxhall Grandland X 1.2 Turbo SRi Nav 5dr

nama GRADE 4

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 29/05/2020 | **Keys** | 2 | **CAP Clean** | £5,725.00 |
| **Year** | 2020 | **Service history** | Yes | **CAP Average** | £4,975.00 |
| **Mileage** | 67,815 Miles Warranted | **Service documents** | Service Book | **CAP Below** | £4,200.00 |
| **Fuel Type** | PETROL | **Number of stamps** | 7 | **Gearbox** | MANUAL |
| **Colour** | GREY | **Last service date** | 07/01/2026 | **Gears** | 6 |
| **VIN** | W0VZRHNS3L6027500 | **Last service miles** | 57,392 | **Doors** | 5 |
| **Body Style** | Hatchback | **MOT Due** | 30/05/2027 | | |

£90 ADDITIONAL FEE
Last Service - 07.01.26 @ 57392 miles (7 services (6 main dealer))

### Tyres

| | | |
|---|---|---|
| **NSF** | KUMHO | 6.0mm |
| **NSR** | WANLI | 5.0mm |
| **OSF** | KUMHO | 6.0mm |
| **OSR** | WANLI | 5.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

## Photos




















**Eastbourne Car Auctions**

# Condition Check




## Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
1 To 5




3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Boot Lid
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door nsr
Dented
Between 10mm + 30mm



14: Door osr
Chipped
Edge Chip



15: Door osf
Poor Previous Repair
Rippled UpTo 30%



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Chipped
1 To 5

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | Fault |
| Airbag light illuminated | OK | Service indicator light illuminated | Fault |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |