46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GP17LFM

Kia Sportage CRDI GT-LINE S ISG

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/08/2017	**Body Style**	Estate	**Last service miles**	89,457
Year	2017	**Keys**	2	**MOT Due**	29/03/2027
Mileage	93,130 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	7
Colour	RED	**Number of stamps**	10	**Doors**	5
VIN	U5YPK815VHL313666	**Last service date**	30/08/2026		

£100 ADDITIONAL FEE
Last Service - 03.08.26 @ 89457 miles (10 main dealer services)

Tyres

NSF	NEXEN	6.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	6.0mm
OSR	NEXEN	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos









GP17 LFM


KIA




11:34




11:41
DAB/FM
AM
Menu
DAB
BBC Radio 1 Dance
Now Playing: We Found Love by Rihanna
Favourites
List
Scan
TA










Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint




7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



9: Qtr Panel nsr
Chipped
1 To 5



10: Bumper Rear
Scratched
Up To 25mm Thru Paint



11: Boot Lid
Scratched
UpTo 25mm Thru Paint



12: Roof
Dented
Over 30mm



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5



16: Door osr
Chipped
Edge Chip



17: Door osf
Scratched
Over 25mm Thru Paint



18: Door osr
Dented
2 Or Less UpTo 10mm



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK