46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YX13HZA

Kia Sportage 2.0 CRDi KX-3 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	01/03/2013	**Colour**	SILVER	**MOT Due**	05/04/2027
Year	2013	**VIN**	U5YPC813NDL276472	**Gearbox**	MANUAL
Mileage	118,279 Miles Warranted	**Body Style**	Estate	**Gears**	6
		Keys	2	**Doors**	5
Fuel Type	DIESEL				

Roof will open and close slowly

Tyres

NSF	BUDGET	5.0mm
NSR	HANKOOK	5.0mm
OSF	BUDGET	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim
- PAS
- Radio/CD
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels

Photos













Ourisida
12.0°C






Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: A Post ns
Chipped
1 To 5



8: Door nsf
Dented
With Paint Damage



9: Door nsr
Dented
Between 10mm + 30mm
Multiple dents



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Other
N/A
N/A
Roof rails scratched



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



14: Boot Lid
Scratched
Over 25mm Thru Paint



15: Parking Sensor Rear
Broken
Replace



16: Qtr Panel osr
Dented
Between 10mm + 30mm




17: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Chipped
1 To 5



20: Door osf
Dented
Between 10mm + 30mm



21: Door osf
Scratched
Over 25mm Thru Paint



22: Wing osf
Chipped
1 To 5



23: Wheel osf
Scratched
Over 50mm



24: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK