46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LS69VDT

Nissan X-Trail 1.7 dCi N-Connecta 5dr [7 Seat]

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/09/2019
Year	2019
Mileage	68,892 Miles Warranted
Fuel Type	DIESEL
Colour	GREY
VIN	JN1JHAT32U0004054
Body Style	Estate

Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	21/05/2026
Last service miles	65,647
MOT Due	30/06/2027
CAP Clean	£8,550.00

CAP Average	£7,450.00
CAP Below	£6,375.00
Gearbox	MANUAL
Gears	6
Doors	5

Last Service - 21.05.2026 at 65647 miles (3 Services)

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Climate control
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Radio/CD
- Front fog lights
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Alarm

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Chipped
Edge Chip



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: B Post ns
Dented
Between 10mm + 30mm



11: Wheel osr
Corroded
Light



12: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Poor Previous Repair
Rippled UpTo 30%



15: Wing osf
Scratched
Over 25mm Thru Paint



16: Roof
Chipped
1 To 5



17: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		