46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WR17UHM

Nissan X-Trail 1.6 DiG-T Visia 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/03/2017	**Keys**	2	**CAP Clean**	£4,500.00
Year	2017	**Service history**	Yes	**CAP Average**	£3,875.00
Mileage	64,424 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£3,250.00
Fuel Type	PETROL	**Number of stamps**	7	**Gearbox**	MANUAL
Colour	RED	**Last service date**	31/03/2026	**Gears**	6
VIN	JN1TDAT32U0006553	**Last service miles**	56,626	**Doors**	5
Body Style	Estate	**MOT Due**	14/04/2027		

Last Service - 31.03.2026 at 56626 miles (7 Services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos









WR17 URH


NISSAN











FM1
11:05
BBC R1
RADIO
MEDIA
SETUP
MENU
ENTER


NISSAN

Condition Check



Damage Photos




1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
1 To 5



3: Door osr
Scratched
Over 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel nsr
Scratched
Up To 50mm



8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint




10: Door nsf
Scratched
UpTo 25mm Thru Paint



11: Wing nsf
Poor Previous Repair
Poor Paint



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK