46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GL18EHG

Skoda Fabia 1.0 TSI SE 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	10/05/2018
Year	2018
Mileage	98,057 Miles Warranted
Fuel Type	PETROL
Colour	BLUE
VIN	TMBFP6NJXJZ167067
Body Style	Hatchback

Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	8
Last service date	13/10/2026
Last service miles	97,563
MOT Due	27/05/2027

CAP Clean	£3,975.00
CAP Average	£3,375.00
CAP Below	£2,800.00
Gearbox	MANUAL
Gears	5
Doors	5

£90 ADDITIONAL FEE
Last Service - 13.10.26 @ 97563 miles (8 services (6 main dealer))

Tyres

NSF	HAIDA	5.0mm
NSR	RAPID	3.0mm
OSF	HAIDA	5.0mm
OSR	RAPID	4.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Solid Paint
- Traction control
- Cloth seat trim


Photos








FABIA




10:29
Please connect a mobile phone.
98057
0.0 / SET


88.3 MHz
SETUP
SOUND
CAR











Condition Check




Damage Photos




1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Scratched
Over 25mm Thru Paint



6: Wheel osr
Scratched
Up To 50mm



7: Qtr Panel osr
Dented
With Paint Damage




8: Bumper Rear
Scratched
Over 100mm Thru Paint




9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Door nsf
Chipped
Multiple Chips



13: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




14: Wing nsf
Dented
With Paint Damage




15: Wheel nsf
Scratched
Over 50mm



16: Bumper Front
Scratched
Over 100mm Thru Paint



17: Bonnet
Chipped
Multiple Chips



18: Roof
Poor Previous Repair
Paint Flake



19: Boot Lid
Dented
Between 10mm + 30mm



20: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK