46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**ST66LBJ**

## Volkswagen Touran 1.6 TDI 115 SE Family 5dr

nama GRADE 4

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Buyer To Apply |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 13/12/2016 | **Body Style** | MPV | **Last service miles** | 69,437 |
| **Year** | 2016 | **Keys** | 2 | **MOT Due** | 07/06/2027 |
| **Mileage** | 82,835 Miles Warranted | **Service history** | Yes | **Gearbox** | MANUAL |
| **Fuel Type** | DIESEL | **Service documents** | Service Book | **Gears** | 6 |
| **Colour** | SILVER | **Number of stamps** | 9 | **Doors** | 5 |
| **VIN** | WVGZZZ1TZHW037210 | **Last service date** | 12/09/2025 | | |

£90 ADDITIONAL FEE
NO V5
LAST SERVICE 12/09/2025 @ 69,437 MILES (9 SERVICES)

### Tyres

| | | |
|---|---|---|
| **NSF** | APOLLO | 6.0mm |
| **NSR** | APOLLO | 6.0mm |
| **OSF** | APOLLO | 6.0mm |
| **OSR** | APOLLO | 6.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos




















# Condition Check




## Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Dented
Between 10mm + 30mm




5: Wing nsf
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Scratched
UpTo 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Sill ns
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



13: Bumper Rear
Poor Previous Repair
Paint Flake




14: Boot Lid
Scratched
Over 25mm Thru Paint



15: Wiper Rear
Broken
Replace



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel osf
Scratched
Over 50mm



22: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |