46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU67VWH

Volkswagen Tiguan 1.4 TSi 150 S 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	27/09/2017	**Keys**	2	**CAP Clean**	£8,875.00
Year	2017	**Service history**	Yes	**CAP Average**	£7,775.00
Mileage	43,392 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£6,650.00
Fuel Type	DIESEL	**Number of stamps**	9	**Gearbox**	MANUAL
Colour	BROWN	**Last service date**	08/07/2026	**Gears**	6
VIN	WVGZZZ5NZHW433259	**Last service miles**	42,185	**Doors**	5
Body Style	Estate	**MOT Due**	12/05/2027		

£90 ADDITIONAL FEE
Last Service - 08.07.26 @ 42185 miles (9 services) Eml light is on car has been plugged in and detects reductant level sensor circuit range performance, cylinder 4 glow plug circuit

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Radio/CD
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking


Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



3: Door osf
Dented
2 Or Less UpTo 10mm



4: Door osr
Dented
2 Or Less UpTo 10mm



5: Bumper Rear
Scratched
Over 100mm Thru Paint



6: Door nsr
Chipped
1 To 5



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Door nsf
Chipped
1 To 5



9: Wing nsf
Chipped
1 To 5



10: Bumper Front
Chipped
1 To 5



11: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault
Airbag light illuminated	OK
ABS light illuminated	OK
Windows	OK

Oil warning light illuminated	OK
DPF light illuminated	OK
Service indicator light illuminated	OK
Radio	OK
Steering	OK