46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HF21YMD

Skoda Karoq 1.6 TDI SE Drive 5dr DSG

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/03/2021	**Keys**	2	**CAP Clean**	£8,850.00
Year	2021	**Service history**	Yes	**CAP Average**	£7,800.00
Mileage	74,045 Miles Warranted	**Service documents**	Printout	**CAP Below**	£6,775.00
Fuel Type	DIESEL	**Number of stamps**	5	**Gearbox**	SEMI AUTO
Colour	GREY	**Last service date**	08/07/2026	**Gears**	7
VIN	TMBKG7NU2M5011034	**Last service miles**	70,987	**Doors**	5
Body Style	Estate	**MOT Due**	19/03/2027		

£90 ADDITIONAL FEE
Last Service - 08.07.26 @ 70987 miles (5 main dealer services)

Tyres

NSF	NEXEN	5.0mm
NSR	KUMHO	5.0mm
OSF	NEXEN	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos








HF21 YMD








BBC Radio2 (H)



325
0.0 / SET







Condition Check



Damage Photos



1: Door osr
Chipped
1 To 5



2: Bumper Rear
Scratched
25 to 100mm Thru Paint



3: Wheel nsr
Corroded
Light



4: Door nsr
Dented
Between 10mm + 30mm



5: Door nsf
Chipped
1 To 5



6: Bonnet
Chipped
1 To 5



7: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK