46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

CV71LZG

Ford Kuga 1.5 EcoBlue Titanium Edition 5dr

nama GRADE 1

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	08/10/2021	**Keys**	2	**CAP Clean**	£9,775.00
Year	2021	**Service history**	Yes	**CAP Average**	£8,675.00
Mileage	43,296 Miles Warranted	**Service documents**	Printout	**CAP Below**	£7,525.00
Fuel Type	DIESEL	**Number of stamps**	4	**Gearbox**	MANUAL
Colour	SILVER	**Last service date**	23/09/2026	**Gears**	6
VIN	WF0FXXWPMFMR36494	**Last service miles**	42,241	**Doors**	5
Body Style	Hatchback	**MOT Due**	07/10/2027		

£90 ADDITIONAL FEE
Last Service - 23.09.26 @ 42241 miles (4 services) Dpf light on
Intermittent engine tap

Tyres

NSF	BUDGET	5.0mm
NSR	PACE	5.0mm
OSF	ROYALBLACK	5.0mm
OSR	GREENLAND	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos


























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip




2: Door nsf
Chipped
Edge Chip



3: Bumper Front
Chipped
Multiple Chips



4: Bonnet
Chipped
1 To 5



5: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK