46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YK70YVG

Seat Arona 1.0 TSI SE Technology [EZ] 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	27/10/2020
Year	2020
Mileage	66,791 Miles Warranted
Fuel Type	PETROL
Colour	WHITE
VIN	VSSZZZKJZMR012045
Body Style	Hatchback

Keys	1
Service history	Yes
Service documents	Printout
Number of stamps	4
Last service date	26/06/2025
Last service miles	44,292
MOT Due	Expired

CAP Clean	£6,325.00
CAP Average	£5,475.00
CAP Below	£4,650.00
Gearbox	MANUAL
Gears	5
Doors	5

£90 ADDITIONAL FEE
Last Service - 26.06.25 @ 44292 miles (4 services)

Tyres

NSF	FALKEN	2.0mm
NSR	NEXEN	4.0mm
OSF	FALKEN	2.0mm
OSR	NEXEN	4.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Radio/CD
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Rear electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking

Photos








YK70 YVG










Condition Check



Damage Photos



1: Qtr Panel osr
Chipped
Edge Chip



2: Bumper Rear
Scratched
Up To 25mm Thru Paint



3: Door nsf
Chipped
1 To 5



4: Bumper Front
Scratched
UpTo 25mm Thru Paint



5: Bonnet
Chipped
1 To 5



6: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK