46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

MA12WDN

Nissan Qashqai+2 1.5 dCi [110] N-Tec+ 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	27/03/2012
Year	2012
Mileage	134,032 Miles Warranted
Fuel Type	DIESEL
Colour	WHITE
VIN	SJNJCAJ10U7117490

Body Style	Hatchback
Keys	1
Service history	Yes
Service documents	Service Book
Number of stamps	5
Last service date	06/01/2024

Last service miles	115,490
MOT Due	11/01/2027
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE
Last Service - 06.01.2024 at 115490 miles (5 Services) Eml light is on car has been plugged in and detects glow plug/heather circuit A, injector circuit/open- cylinder 4

Tyres

NSF	HIFLY	3.0mm
NSR	HIFLY	5.0mm
OSF	HIFLY	3.0mm
OSR	HIFLY	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Seat Back Cover osf
Scuffed
UpTo 25mm



3: Bonnet
Poor Previous Repair
Rippled UpTo 30%



4: Bumper Front Moulding
Broken
Replace



5: Bumper Front
Chipped
Multiple Chips



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Wheel nsf
Scratched
Over 50mm



8: Wing nsf
Chipped
1 To 5



9: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




10: Door nsf
Dented
Between 10mm + 30mm
Multiple dents



11: Door nsf
Chipped
Multiple Chips



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Bumper Rear
Insecure
Action Required



16: Bumper Rear
Dented
With Paint Damage



17: Boot Lid
Poor Previous Repair
Poor Paint



18: Qtr Panel osr
Chipped
1 To 5



19: Wheel osr
Scratched
Over 50mm



20: Door osr
Dented
Between 10mm + 30mm
Multiple dents




21: Door osf
Dented
Over 30mm



22: Door osf
Chipped
Edge Chip




23: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



24: A Post os
Chipped
1 To 5



25: Wing osf
Dented
Between 10mm + 30mm



26: Wing osf
Chipped
1 To 5



27: Wheel osf
Scratched
Over 50mm



28: Other
N/A
N/A
Roof rails scratched



29: Screen Front
Chipped
UpTo 10mm



30: Door Pad osf
Scuffed
Over 25mm



31: Seat Base Cover osr
Torn
Over 3mm



32: Seat Base Cover nsr
Holed
UpTo 3mm



33: Door Pad nsf
Scuffed
Over 25mm



34: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		