46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KS73JAU

Vauxhall Mokka 100kW Ultimate 50kWh 5dr Auto

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	VAT Qualifying
V5	Photocopy

Details

Reg. date	14/11/2023	**Body Style**	Hatchback	**Last service miles**	25,986
Year	2023	**Keys**	2	**MOT Due**	04/10/2027
Mileage	29,836 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	Electric	**Service documents**	Printout	**Gears**	1
Colour	BLUE	**Number of stamps**	3	**Doors**	5
VIN	VXKUKZKXZPW116266	**Last service date**	21/05/2026		

Last Service - 21.05.2026 at 25986 miles (3 main dealer Services) Type 2 charging cable

Tyres

NSF	MICHELIN	3.0mm
NSR	MICHELIN	Damaged
OSF	MICHELIN	3.0mm
OSR	AVON	3.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim

Photos

















Eco
Charge
Power
P
0
38 s

10:16
Hi
Search...


10:16
Hi
A/C

Eco
Charge
Power
R
0
38 s
READY

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



5: A Post ns
Chipped
1 To 5



6: Door nsf
Chipped
Edge Chip



7: Door nsr
Scratched
UpTo 25mm Thru Paint




8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Scratched
Over 25mm Thru Paint



12: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



13: Door osf
Chipped
Edge Chip



14: Roof
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm



16: Wheel osf
Scratched
Over 50mm



17: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



18: Seat Base Cover osf
Soiled
Light



19: Tyre nsr
Damaged
Replace



20: Wing nsf
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK