46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

NV12KMM

Kia Venga 1.6 2 5dr Auto

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	03/07/2012	**Colour**	WHITE	**MOT Due**	30/07/2027
Year	2012	**VIN**	U5YEH812MDL028203	**Gearbox**	AUTOMATIC
Mileage	88,141 Miles Warranted	**Body Style**	Hatchback	**Gears**	4
		Keys	2	**Doors**	5
Fuel Type	PETROL				

Tyres

NSF	TRIANGLE	4.0mm
NSR	WESTLAKE	5.0mm
OSF	TRIANGLE	4.0mm
OSR	FALKEN	5.0mm
Spare		

Features

- Bluetooth connection
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking

Photos





















Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



3: Door osf
Dented
With Paint Damage



4: Door osr
Dented
With Paint Damage



5: Qtr Panel osr
Dented
Over 30mm



6: Wheel osr
Corroded
Light



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Qtr Panel nsr
Dented
With Paint Damage



10: Door nsr
Dented
Over 30mm



11: Door nsf
Chipped
Edge Chip



12: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint




13: Wheel nsf
Corroded
Light



14: Bumper Front
Scratched
25 to 100mm Thru Paint




15: Bonnet
Chipped
1 To 5




16: Roof
Poor Previous Repair
Poor Paint



17: A Post ns
Poor Previous Repair
Paint Flake



18: A Post os
Poor Previous Repair
Paint Flake



19: Screen Front
Cracked
Replace



20: Door Pad nsf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK