46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU19NGE

Volvo XC90 2.0 D5 PowerPulse Momentum 5dr AWD Geartronic

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	27/03/2019
Year	2019
Mileage	31,999 Miles Warranted
Fuel Type	DIESEL
Colour	GREY
VIN	YV1LF68UCK1501798

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	7
Last service date	27/03/2026

Last service miles	31,103
MOT Due	26/03/2027
Gearbox	AUTOMATIC
Gears	8
Doors	5

£90 ADDITIONAL FEE
Last Service - 27.03.26 @ 31103 miles (7 services)

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	6.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Trip computer
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim


Photos
















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door nsf
Chipped
1 To 5



3: Door nsf
Dented
2 Or Less UpTo 10mm



4: Wing nsf
Chipped
1 To 5



5: Bumper Front
Chipped
1 To 5



6: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK