46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

OE72SNV

Genesis GV70 2.5T Luxury 5dr Auto AWD

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	18/11/2022	**Body Style**	MPV	**MOT Due**	18/11/2026
Year	2022	**Keys**	2	**Gearbox**	AUTOMATIC
Mileage	22,276 Miles Warranted	**Service history**	Yes	**Gears**	8
Fuel Type	PETROL	**Service documents**	Electronic / Online	**Doors**	5
Colour	GREY	**Number of stamps**	2		
VIN	KMTMA81BSPU092940	**Last service miles**	17,373		

£90 ADDITIONAL FEE
Last Service - @ 17373 miles (2 services) - confirmed by Genesis Customer Service

Tyres

NSF	MICHELIN	Damaged
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear electric windows
- Drivers airbag
- Central locking
- Rear headrests
- Passenger airbag
- Remote central locking

Photos




















Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
Edge Chip



3: Door osr
Dented
2 Or Less UpTo 10mm



4: Door osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm




6: Wheel nsr
Scratched
Over 50mm




7: Door nsr
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Chipped
1 To 5



10: Screen Front
Chipped
UpTo 10mm



11: Roof
Poor Previous Repair
Paint Flake



12: Tyre nsf
Damaged
Replace

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK