46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GK13XCR

Ford Kuga 2.0 TDCi Titanium 5dr 2WD

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Photocopy

Details

Reg. date	30/03/2013	**Body Style**	Hatchback	**Last service miles**	137,026
Year	2013	**Keys**	2	**MOT Due**	30/03/2027
Mileage	137,897 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	11	**Doors**	5
VIN	WF0AXXWPMADM19113	**Last service date**	16/04/2026		

Last Service - 16.04.2026 at 137026 miles (11 Services)
NO V5- PHOTOCOPY

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Radio/CD
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos
























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Door Pad osr
Scuffed
Over 25mm



3: Bonnet
Scratched
Over 25mm Thru Paint




4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Wing nsf
Chipped
1 To 5




7: Screen Front
Chipped
Over 10mm



8: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



9: Door nsf
Dented
Over 2 UpTo 10mm



10: Door nsf
Scratched
UpTo 25mm Thru Paint



11: Door nsr
Chipped
Edge Chip



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



16: Boot Lid
Dented
With Paint Damage



17: Qtr Panel osr
Chipped
1 To 5




18: Wheel osr
Scratched
Up To 50mm



19: Door osr
Scratched
Over 25mm Thru Paint



20: Door osf
Dented
Between 10mm + 30mm



21: Door osf
Scratched
Over 25mm Thru Paint



22: Wing osf
Scratched
Over 25mm Thru Paint



23: Wing osf
Dented
Between 10mm + 30mm



24: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK