46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY68KWZ

Ford Fiesta 1.5 TDCi 120 Titanium 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/10/2018
Year	2018
Mileage	87,633 Miles Warranted
Fuel Type	DIESEL
Colour	BLACK
VIN	WF0JXXGAHJJB69360

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	1
Last service date	26/09/2019

Last service miles	11,047
MOT Due	Expired
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE
LAST SERVICE 26/09/2019 @ 11,047 MILES (1 SERVICE) Noisy front suspension/ spring

Tyres

NSF	COMFORSER	6.0mm
NSR	HANKOOK	Damaged
OSF	SUNNY	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking

Photos








GY68 KWZ





87633.9 mls
See manual


ford fiesta
GY68 KWZ
Black


TA
14:59 15°
18.0°
DAB
Sources
Stations
11D
Traffic (TA)
Presets
BBC RSL
BBC R3
BBC R4
GB News
BBC R1
BBC R2
Audio
Phone
Navigation
Mobile apps
Settings
VOL
TUNE


TA
14:59 15°
18.0°
Brodrick Road
Destination
Eastbourne
Menu
Audio
Phone
Navigation
Mobile apps
Settings
VOL
TUNE



Please check surroundings for safety
VOL
TUNE








Condition Check



Damage Photos




1: Other
N/A
N/A
Carpet in boot soiled



2: Bonnet
Chipped
Multiple Chips




3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
With Paint Damage



7: A Post ns
Scratched
Over 25mm Thru Paint



8: B Post ns
Scratched
Over 25mm Thru Paint



9: Door nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Insecure
Action Required



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Roof
Scratched
Over 25mm Thru Paint



16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Dented
Between 10mm + 30mm
Multiple dents



18: Door osf
Dented
Over 30mm



19: Door osf
Chipped
Edge Chip



20: A Post os
Scratched
Over 25mm Thru Paint



21: Door Mirror Assy osf
Broken
Replace



22: Flasher Side Repeater os
Broken
Replace



23: Wing osf
Dented
With Paint Damage



24: Wheel osf
Scratched
Over 50mm



25: Screen Front
Chipped
UpTo 10mm



26: Tyre nsr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK