46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YL19KKE

Skoda Kodiaq 1.5 TSI Sport Line 4x4 5dr DSG [7 Seat]

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/05/2019	**Keys**	2	**CAP Clean**	£14,800.00
Year	2019	**Service history**	Yes	**CAP Average**	£13,500.00
Mileage	54,639 Miles Warranted	**Service documents**	Printout	**CAP Below**	£12,150.00
Fuel Type	PETROL	**Number of stamps**	6	**Gearbox**	SEMI AUTO
Colour	GREY	**Last service date**	12/11/2025	**Gears**	7
VIN	TMBMB7NS1K8066849	**Last service miles**	47,075	**Doors**	5
Body Style	Estate	**MOT Due**	08/10/2027		

£90 ADDITIONAL FEE
LAST SERVICE 12/11/2025 @ 47,075 MILES (6 SERVICES)

Tyres

NSF	TRISTAR	Damaged
NSR	TRISTAR	5.0mm
OSF	TRISTAR	4.0mm
OSR	TRISTAR	Damaged
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5




3: Door osr
Chipped
1 To 5



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Wheel osr
Corroded
Light



6: Qtr Panel nsr
Dented
Over 30mm



7: Wheel nsr
Scratched
Over 50mm



8: Door nsr
Chipped
1 To 5



9: Door nsf
Chipped
1 To 5



10: Wheel nsf
Scratched
Over 50mm



11: Wing nsf
Chipped
1 To 5



12: Bumper Front
Scratched
UpTo 25mm Thru Paint



13: Screen Front
Chipped
UpTo 10mm



14: Handle Inner osf
Damaged
Replace



15: Tyre nsf
Damaged
Replace



16: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK