46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LJ68MBF

Ford Kuga 1.5 EcoBoost 176 ST-Line X 5dr Auto

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/12/2018	**Body Style**	Hatchback	**Last service miles**	39,481
Year	2018	**Keys**	2	**MOT Due**	09/09/2027
Mileage	40,351 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	GREY	**Number of stamps**	7	**Doors**	5
VIN	WF0AXXWPMAJA31790	**Last service date**	10/09/2026		

Last Service - 10.09.26 @ 39481 miles (7 services) Slight engine tapping

Tyres

NSF	GOODYEAR	5.0mm
NSR	CONTINENTAL	4.0mm
OSF	GOODYEAR	5.0mm
OSR	ACCELERA	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Chipped
1 To 5



6: Door nsr
Chipped
Edge Chip



7: Wheel nsr
Scratched
Over 50mm



8: C Post os
Dented
Between 10mm + 30mm
Multiple dents



9: Door osr
Chipped
1 To 5



10: Door osf
Chipped
Edge Chip



11: Wheel osf
Scratched
Over 50mm



12: Screen Front
Chipped
UpTo 10mm



13: Roof
Chipped
Edge Chip



14: Bumper Front
Poor Previous Repair
Poor Paint



15: Bumper Rear
Poor Previous Repair
Poor Colour

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		