46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GL70OKB

Audi A4 40 TFSI 204 S Line 4dr S Tronic

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/12/2020	**Keys**	2	**CAP Clean**	£13,200.00
Year	2020	**Service history**	Yes	**CAP Average**	£12,050.00
Mileage	52,736 Miles Warranted	**Service documents**	Printout	**CAP Below**	£10,950.00
Fuel Type	PETROL	**Number of stamps**	3	**Gearbox**	SEMI AUTO
Colour	GREY	**Last service date**	22/05/2023	**Gears**	7
VIN	WAUZZZF48MN004301	**Last service miles**	26,899	**Doors**	4
Body Style	Saloon	**MOT Due**	08/12/2026		

£90 ADDITIONAL FEE
Last Service - 22.05.23 @ 26899 miles (3 main dealer services)

Tyres

NSF	BRIDGESTONE	Damaged
NSR	GOODYEAR	Damaged
OSF	BRIDGESTONE	4.0mm
OSR	MICHELIN	Damaged
Spare		

Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos








GL70 0KB




Date & time
14:28
Tuesday
10.11.2026


Search


AUDI
A4
GREY



Rear view







Condition Check



Damage Photos




1: Tyre nsf
Damaged
Replace



2: Tyre nsr
Damaged
Replace



3: Tyre osr
Damaged
Replace



4: Bonnet
Chipped
1 To 5



5: Bumper Front
Cracked
Over 25mm



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Dented
With Paint Damage



9: Door nsr
Dented
Between 10mm + 30mm



10: Door nsr
Chipped
1 To 5



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



13: Bumper Rear
Cracked
UpTo 25mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
1 To 5



17: Door osf
Chipped
Edge Chip



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK