46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

NK13ZNU

Audi A6 2.0 TDI S Line 4dr Multitronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/03/2013
Year	2013
Mileage	132,291 Miles Warranted
Fuel Type	DIESEL
Colour	BLACK
VIN	WAUZZZ4G0DN110223
Body Style	Saloon

Keys	1
Service history	Yes
Service documents	Printout
Number of stamps	4
Last service date	07/12/2016
Last service miles	35,999
MOT Due	27/01/2027

CAP Clean	£2,475.00
CAP Average	£2,125.00
CAP Below	£1,775.00
Gearbox	CVT
Gears	8
Doors	4

Last Service - 07.12.16 @ 35999 miles (4 services) Parking sensor faulty
Oil leak

Tyres

NSF	TRIANGLE	5.0mm
NSR	AUTOGREEN	5.0mm
OSF	TRIANGLE	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Up To 50mm



3: Wheel nsr
Scratched
Over 50mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing osf
Chipped
1 To 5



6: Door osf
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Chipped
1 To 5



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Door nsf
Poor Previous Repair
Poor Paint



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK