46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EK11VWG

Ford Fiesta 1.6 TDCi [95] Econetic 5dr [AC]

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	08/04/2011	**VIN**	WF0JXXGAJJBE20123	**CAP Average**	£370.00
Year	2011	**Body Style**	Hatchback	**CAP Below**	£150.00
Mileage	107,731 Miles Warranted	**Keys**	1	**Gearbox**	MANUAL
		MOT Due	04/12/2026	**Gears**	5
Fuel Type	DIESEL	**CAP Clean**	£770.00	**Doors**	5
Colour	MAUVE/PURPLE				

Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	LASSA	5.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- PAS
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Central locking
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Steel wheels

Photos










11 °C
107731 MLS
4
5
40
30
20
10
60
40
20





532







Condition Check



Damage Photos



1: Seat Base Cover osr
Soiled
Light



2: Other
N/A
N/A
Carpet in boot soiled



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Cracked
Over 25mm



5: Wing nsf
Dented
With Paint Damage



6: Wheel Trim nsf
Missing
Replace




7: Door Mirror Assy nsf
Broken
Replace



8: A Post ns
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Dented
Over 30% Of Panel



10: Door nsr
Dented
Over 30% Of Panel



11: Sill ns
Dented
With Paint Damage




12: B Post ns
Dented
With Paint Damage



13: C Post ns
Scratched
Over 25mm Thru Paint



14: Qtr Panel nsr
Dented
With Paint Damage




15: Bumper Rear
Cracked
Over 25mm




16: Boot Lid
Dented
With Paint Damage



17: Qtr Panel osr
Dented
With Paint Damage



18: Door osr
Scratched
Over 25mm Thru Paint



19: Sill os
Scratched
Over 25mm Thru Paint



20: Door osf
Scratched
Over 25mm Thru Paint



21: Wing osf
Dented
With Paint Damage



22: Door Mirror Assy osf
Broken
Replace



23: Roof
Scratched
Over 25mm Thru Paint



24: C Post os
Scratched
Over 25mm Thru Paint



25: Screen Front
Cracked
Replace



26: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK