46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY60LSO

Volkswagen Scirocco 2.0 TSI 210 GT 3dr DSG

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	04/11/2010	**Colour**	BLACK	**MOT Due**	08/11/2027
Year	2010	**VIN**	WVWZZZ13ZBV011472	**Gearbox**	SEMI AUTO
Mileage	112,994 Miles Warranted	**Body Style**	Coupe	**Gears**	6
		Keys	2	**Doors**	2
Fuel Type	PETROL				

Tyres

NSF	BUDGET	5.0mm
NSR	GENERAL TIRE	5.0mm
OSF	BUDGET	Damaged
OSR	BUDGET	Damaged
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Radio/CD
- Climate control
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Front electric windows
- Passenger airbag
- Remote central locking

Photos












Radio 1










Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
Over 30mm



3: A Post os
Chipped
1 To 5



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip




6: Wheel osr
Scratched
Over 50mm




7: Qtr Panel osr
Poor Previous Repair
Poor Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Lamp nsr
Broken
Replace



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Chipped
1 To 5



13: Door nsf
Chipped
Edge Chip



14: Door nsf
Chipped
1 To 5




15: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint




16: Wheel nsf
Scratched
Over 50mm



17: Bumper Front
Scratched
Over 100mm Thru Paint



18: Bonnet
Chipped
Multiple Chips



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Chipped
1 To 5



21: Tyre osf
Damaged
Replace



22: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK