46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HV71NLY

Skoda Scala 1.5 TSI SE L 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	13/09/2021	**Body Style**	Hatchback	**Last service miles**	65,958
Year	2021	**Keys**	2	**MOT Due**	12/09/2027
Mileage	69,309 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	BLUE	**Number of stamps**	6	**Doors**	5
VIN	TMBFK6NW3M3113658	**Last service date**	08/09/2026		

£90 ADDITIONAL FEE
Last Service - 08.09.26 @ 65958 miles (6 services (3 main dealer))
Timing belt replaced 08.09.26 @ 65958 miles

Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos









HV71 NLY




0
mph
Please switch on light.




Smooth UK (DAB)
Lij Rock
Abs 80s
Empty










Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
1 To 5



4: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




5: Bumper Rear
Dented
With Paint Damage



6: Wheel nsr
Scratched
Up To 50mm




7: Door nsr
Chipped
1 To 5



8: Bumper Front
Chipped
1 To 5



9: Bonnet
Chipped
1 To 5



10: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK