46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

RV66ZXD

Ford Kuga 2.0 TDCi 150 Titanium 5dr 2WD

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	23/09/2016	**Keys**	2	**CAP Clean**	£2,900.00
Year	2016	**Service history**	Yes	**CAP Average**	£2,375.00
Mileage	89,000 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£1,875.00
Fuel Type	DIESEL	**Number of stamps**	4	**Gearbox**	MANUAL
Colour	GREEN	**Last service date**	26/08/2022	**Gears**	6
VIN	WF0AXXWPMAGB31367	**Last service miles**	58,344	**Doors**	5
Body Style	Hatchback	**MOT Due**	30/08/2027		

Last Service - 26.08.2022 at 58344 miles (4 Services)

Tyres

NSF	TOYO	6.0mm
NSR	ACCELERA	5.0mm
OSF	TOYO	6.0mm
OSR	ACCELERA	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking


Photos


















Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
With Paint Damage



3: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Door osf
Dented
Between 10mm + 30mm



6: Door osr
Chipped
1 To 5



7: Wheel osr
Scratched
Over 50mm



8: Boot Lid
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Dented
Over 30mm



11: Door nsf
Dented
Between 10mm + 30mm



12: Wing nsf
Scratched
UpTo 25mm Thru Paint



13: Wing nsf
Chipped
1 To 5



14: Wheel nsf
Scratched
Over 50mm



15: Bumper Front
Chipped
Multiple Chips



16: Bonnet
Chipped
1 To 5



17: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



18: Other
N/A
N/A
Roof rails scratched

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK