46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KW15CYA

Kia Sportage 1.6 GDi ISG 2 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/05/2015	**Body Style**	Estate	**Last service miles**	64,635
Year	2015	**Keys**	2	**MOT Due**	23/07/2027
Mileage	70,827 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	BLACK	**Number of stamps**	8	**Doors**	5
VIN	U5YPC814LFL667319	**Last service date**	12/12/2025		

Last Service - 12.12.2025 at 64635 miles (8 Services) Low clutch
Sunroof opens and shuts very slowly

Tyres

NSF	GT RADIAL	5.0mm
NSR	GT RADIAL	5.0mm
OSF	GT RADIAL	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- PAS
- Radio/CD
- Full size spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos




















Eastbourne Car Auctions


Condition Check




Damage Photos



1: Centre Console Front
Scuffed
Over 25mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Chipped
1 To 5



4: Bumper Front
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint




7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsf
Chipped
Multiple Chips



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Door nsr
Dented
Over 30mm



11: Wheel nsr
Scratched
Over 50mm



12: B Post ns
Dented
Over 2 UpTo 10mm



13: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Boot Lid
Scratched
UpTo 25mm Thru Paint



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Door osr
Chipped
Over 5mm



18: Door osr
Dented
Over 2 UpTo 10mm



19: Door osf
Scratched
Over 25mm Thru Paint



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK