46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

WN14YKT

Jaguar XF 2.2d [200] Premium Luxury 4dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/06/2014	**Body Style**	Saloon	**Last service miles**	25,153
Year	2014	**Keys**	2	**MOT Due**	20/12/2026
Mileage	133,621 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	8
Colour	BLUE	**Number of stamps**	3	**Doors**	4
VIN	SAJAC06K1FDU42745	**Last service date**	05/05/2017		

Last Service - 05.05.2017 at 25153 miles (3 MAIN DEALER Services)

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	Damaged
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Radio/CD
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos




























Eastbourne Car Auctions

Condition Check




Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Tyre osf
Damaged
Replace



3: Bonnet
Scratched
Over 25mm Thru Paint



4: Bumper Front
Poor Previous Repair
Paint Flake



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint




7: Door nsf
Scratched
Over 25mm Thru Paint




8: B Post ns
Scratched
Over 25mm Thru Paint



9: Door nsf
Dented
Over 2 UpTo 10mm



10: Door nsr
Dented
Between 10mm + 30mm
Multiple dents




11: Door nsr
Scratched
Over 25mm Thru Paint




12: Qtr Panel nsr
Chipped
1 To 5



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Scratched
Up To 25mm Thru Paint



15: Bumper Rear
Scratched
25 to 100mm Thru Paint



16: Boot Lid
Chipped
1 To 5



17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Wheel osr
Scratched
Over 50mm



19: Roof
Scratched
Over 25mm Thru Paint




20: Door osr
Dented
Between 10mm + 30mm



21: Door osr
Chipped
Edge Chip



22: Door osr
Chipped
1 To 5




23: Door osf
Poor Previous Repair
Poor Paint



24: Wing osf
Scratched
Over 25mm Thru Paint



25: Wheel osf
Scratched
Over 50mm



26: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK