46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YH14YPK

Vauxhall Corsa 1.2 Sting 3dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/03/2014	**Body Style**	Hatchback	**Last service miles**	61,441
Year	2014	**Keys**	2	**MOT Due**	18/04/2027
Mileage	63,772 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	GREEN	**Number of stamps**	3	**Doors**	3
VIN	W0L0SDL08E6033148	**Last service date**	28/08/2026		

£90 ADDITIONAL FEE
Last Service - 28.08.2026 at 61441 miles (3 Services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	DOUBLESTAR	5.0mm
Spare		

Features

- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Alloy wheels
- Electric door mirrors
- Metallic Paint
- Central locking

Photos
















Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Other
N/A
N/A



4: A Post os
Chipped
1 To 5



5: Door osf
Poor Previous Repair
Paint Flake



6: Qtr Panel osr
Chipped
1 To 5



7: Wheel osr
Scratched
Up To 50mm



8: Bumper Rear
Dented
With Paint Damage




9: Boot Lid
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Door nsf
Chipped
1 To 5



13: Door nsf
Chipped
Edge Chip



14: Wheel nsf
Scratched
Over 50mm



15: Bonnet
Dented
With Paint Damage

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK