46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GN15YMW

Kia Rio 1.25 SR7 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/03/2015	**Body Style**	Hatchback	**Last service miles**	28,863
Year	2015	**Keys**	2	**MOT Due**	20/03/2027
Mileage	62,430 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	YELLOW	**Number of stamps**	4	**Doors**	5
VIN	KNADN511LF6503145	**Last service date**	08/04/2019		

£90 ADDITIONAL FEE
Last Service - 08.04.2019 at 28863 miles (4 Services)

Tyres

NSF	MAZZINI	6.0mm
NSR	MAZZINI	6.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osr
Chipped
Multiple Chips



5: Qtr Panel osr
Dented
With Paint Damage



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Boot Lid
Chipped
1 To 5



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Wheel nsr
Scratched
Over 50mm



11: Door nsf
Chipped
1 To 5



12: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Wing nsf
Chipped
1 To 5




15: Bumper Front
Scratched
Over 100mm Thru Paint



16: Bonnet
Chipped
1 To 5




17: A Post os
Chipped
1 To 5



18: Roof
Chipped
1 To 5



19: Wing osf
Dented
Between 10mm + 30mm



20: Bonnet
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK