46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GK66GNF

Vauxhall Adam 1.4i Glam 3dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/09/2016
Year	2016
Mileage	102,595 Miles Warranted
Fuel Type	PETROL
Colour	BLACK
VIN	W0L0MAP08G6065153

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	10
Last service date	10/08/2026

Last service miles	100,751
MOT Due	31/08/2027
Gearbox	MANUAL
Gears	5
Doors	3

£90 ADDITIONAL FEE
Last Service - 10.08.2026 at 100751 miles (10 services 9 main dealer Services)

Tyres

NSF	NEXEN	1.0mm
NSR	RAPID	5.0mm
OSF	NEXEN	3.0mm
OSR	RAPID	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Electric door mirrors
- Rear headrests
- Passenger airbag
- Remote central locking
- Telephone
- Fixed panoramic glass roof
- Metallic Paint
- Traction control
- Cloth seat trim
- Radio/CD
- Air conditioning
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos















www.ebca.co.uk





Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5




3: Door osf
Poor Previous Repair
Poor Paint




4: Qtr Panel osr
Poor Previous Repair
Paint Flake



5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel nsr
Dented
Over 30mm



7: Door nsf
Chipped
Multiple Chips



8: Wing nsf
Poor Previous Repair
Paint Flake



9: Wheel nsr
Scratched
Over 50mm



10: Wheel nsf
Scratched
Over 50mm



11: Bumper Front
Chipped
Multiple Chips



12: Bonnet
Chipped
Multiple Chips



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK