46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

MT15HNZ

Nissan Juke 1.2 DiG-T Tekna 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/07/2015	**Body Style**	Hatchback	**Last service miles**	77,024
Year	2015	**Keys**	2	**MOT Due**	20/11/2026
Mileage	85,309 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	RED	**Number of stamps**	1	**Doors**	5
VIN	SJNFEAF15U7130670	**Last service date**	08/11/2024		

£100 ADDITIONAL FEE
Last Service - 08.11.24 @ 77024 miles (1 services)

Tyres

NSF	COMFORSER	5.0mm
NSR	COMFORSER	5.0mm
OSF	COMFORSER	5.0mm
OSR	TOYO	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking


Photos








WT15 HNZ






85309 miles
38 miles



AUDIO OFF
11:48
MAP
NAV INFO
SETUP
Menu
CLIMATE
D-MODE








MAP
NAV INFO
SETUP
Ensure it is safe before manoeuvring








Condition Check



Damage Photos



1: Other
N/A
N/A
Arm rest damaged



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Other
N/A
N/A
Trim scratched



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Headlamp ns
Broken
Replace



8: A Post ns
Chipped
1 To 5



9: Door nsf
Dented
Over 30mm



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Other
N/A
N/A
Rear lamp scratched



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
1 To 5



17: Door osf
Scratched
Over 25mm Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Aperture Seal osf
Broken
Replace



21: Roof
Rusted
Over 5mm



22: A Post os
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK