46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EF14WVK

BMW X1 sDrive 20d xLine 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	05/07/2014	**Colour**	SILVER	**Gearbox**	MANUAL
Year	2014	**VIN**	WBAVN92040VR59572	**Gears**	6
Mileage	89,325 Miles Warranted	**Body Style**	Estate	**Doors**	5
		MOT Due	12/07/2027		
Fuel Type	DIESEL				

Tyres

NSF	BUDGET	Damaged
NSR	AVON	5.0mm
OSF	BUDGET	5.0mm
OSR	AVON	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim
- Heated front seat
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels

Photos











Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Tyre nsf
Damaged
Replace



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Chipped
1 To 5



5: Other
N/A
N/A
Headlight clouded



6: Wheel nsf
Scratched
Over 50mm



7: Screen Front
Chipped
UpTo 10mm



8: Door nsf
Chipped
1 To 5



9: Door nsf
Dented
Between 10mm + 30mm



10: Door nsr
Dented
Over 30mm




11: Door nsr
Chipped
1 To 5



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Chipped
1 To 5



14: Boot Lid
Scratched
UpTo 25mm Thru Paint



15: Roof
Dented
Over 30mm



16: Qtr Panel osr
Dented
Over 2 UpTo 10mm



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
With Paint Damage



19: Door osf
Chipped
Edge Chip



20: Wing osf
Dented
Between 10mm + 30mm



21: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK