46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

AU14SXT

Ford Fiesta 1.0 EcoBoost Zetec 3dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/03/2014	**Body Style**	Hatchback	**Last service miles**	50,089
Year	2014	**Keys**	2	**MOT Due**	26/11/2027
Mileage	74,461 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	5
Colour	SILVER	**Number of stamps**	8	**Doors**	3
VIN	WF0CXXGAKCEY31110	**Last service date**	26/11/2024		

Last Service - 26.11.24 @ 50089 miles (8 services)
Cambelt replaced 18.11.24 @ 50000 miles
Mileage input error in MOT history 2024 and 2025

Tyres

NSF	BUDGET	5.0mm
NSR	SAILUN	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	4.0mm
Spare		

Features

- Bluetooth connection
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels
- Telephone
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wing osf
Dented
Over 30mm



2: Door osf
Dented
With Paint Damage



3: Qtr Panel osr
Scratched
Over 25mm Thru Paint



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Bumper Rear
Chipped
1 To 5



6: Qtr Panel nsr
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5




8: Wing nsf
Chipped
1 To 5



9: Wheel nsf
Scratched
Over 50mm



10: Bonnet
Chipped
1 To 5



11: Bumper Front
Scratched
25 to 100mm Thru Paint



12: Bumper Front
Chipped
1 To 5



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK