46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX63LSV

Mitsubishi Shogun 3.2 DI-DC [197] SG3 5dr Auto

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	28/09/2013	**VIN**	JMALYV98WEJ400116	**CAP Average**	£6,800.00
Year	2013	**Body Style**	Estate	**CAP Below**	£5,800.00
Mileage	83,102 Miles Warranted	**Keys**	2	**Gearbox**	AUTOMATIC
		MOT Due	27/09/2027	**Gears**	5
Fuel Type	DIESEL	**CAP Clean**	£7,775.00	**Doors**	5
Colour	GREY				

£100 ADDITIONAL FEE Roof need attention
Front headlamp flicker

Tyres

NSF	MICHELIN	6.0mm
NSR	MICHELIN	6.0mm
OSF	MICHELIN	6.0mm
OSR	MICHELIN	6.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

Photos

































Eastbourne Car Auctions

Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Bumper Front
Chipped
1 To 5



5: Wing nsf
Chipped
1 To 5



6: Screen Front
Cracked
Replace



7: Door nsf
Chipped
1 To 5



8: Door nsr
Chipped
1 To 5



9: Bumper Rear
Scratched
25 to 100mm Thru Paint




10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Chipped
1 To 5



12: Door osr
Scratched
UpTo 25mm Thru Paint



13: Door osf
Chipped
1 To 5



14: Wing osf
Dented
Between 10mm + 30mm



15: Wing Front Arch Extension os
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		