46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LF64FDM

Land Rover Freelander 2.2 SD4 SE Tech 5dr Auto

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	04/09/2014	**Body Style**	Estate	**Last service miles**	188,337
Year	2014	**Keys**	2	**MOT Due**	26/07/2026
Mileage	194,889 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	Diesel	**Service documents**	Printout	**Gears**	6
Colour	GREEN	**Number of stamps**	12		
VIN	SALFA2AE6FH422581	**Last service date**	14/07/2025		

£90 ADDITIONAL FEE
Last Service - 14.07.2025 at 188337 miles (12 services)

Boot only releases by key

Tyres

NSF	PIRELLI	2.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	Worn
OSR	PIRELLI	4.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Side airbags
- Leather seat trim

Photos

Nav
13:08
BRAMPTON ROAD, EAST...
HOME MENU
NAV
PHONE
AUDIO VIDEO
SETUP
MODE

Parking aid alert
Take care when manoeuvring
Display off
HOME MENU
NAV
PHONE
AUDIO VIDEO
SETUP
MODE

Condition Check



Damage Photos

1: Bumper Rear
Scratched
Over 100mm Thru Paint

2: Boot Lid
Dented
Over 2 UpTo 10mm

No Image

3: Boot Lid
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel nsr
Dented
With Paint Damage

5: Wheel nsr
Scratched
Over 50mm

6: Door nsr
Scratched
Over 25mm Thru Paint

7: Door nsf
Scratched
Over 25mm Thru Paint

8: Wing nsf
Dented
With Paint Damage

9: Wheel nsf
Scratched
Over 50mm

10: Bumper Front
Scratched
Over 100mm Thru Paint

11: Bonnet
Rusted
UpTo 5mm

12: Wing osf
Dented
With Paint Damage

13: Wheel osf
Scratched
Over 50mm

14: Door osf
Scratched
Over 25mm Thru Paint

15: Handle Outer osf
Missing
Replace

16: Door osr
Scratched
Over 25mm Thru Paint

17: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

No Image

18: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

19: Wheel osr
Scratched
Over 50mm

20: Other
N/A
N/A



21: Roof Lining
Torn
UpTo 3mm

22: Door Mirror Assy osf
Broken
Replace

23: Door Mirror Assy nsf
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK