46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

DK18XRG

Volkswagen Golf 2.0 TSI GTI 3dr DSG

nama GRADE 2

Inspection		Vehicle	
Serious Damage?	No	**VAT**	Margin
		V5	Present

Details

Reg. date	08/03/2018	**Body Style**	Hatchback	**Last service miles**	50,916
Year	2018	**Keys**	1	**MOT Due**	15/07/2026
Mileage	84,577 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	Petrol	**Service documents**	Printout	**Gears**	6
Colour	SILVER	**Number of stamps**	4	**Doors**	3
VIN	WVWZZZAUZJW178027	**Last service date**	07/10/2022		

Last service 07/10/2022 at 50916 miles (4 main dealer services). Car cuts out when idling
Intermittent EML light car has been plugged in but shows no codes

Tyres

NSF	PIRELLI	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Space saver spare wheel
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos



16:38
Since start
Avg. ---
mpg
Consumption
Please switch on
dipped beam headlight.
60
mi
Range
84577 mi

RADIO
MEDIA
PHONE
VOICE
NAV
APP
CAR
MENU
Navigation database not available.
AUTO
MENU
SYNC
A/C

RADIO
MEDIA
PHONE
VOICE
NAV
APP
CAR
MENU
16:38
105.8 MHz
Empty
Band
FM
Station list
Memory
Settings
AUTO
MENU
SYNC
A/C

RADIO
Parkpilot
MEDIA
PHONE
VOICE
APP
CAR
MENU
Look! Safe to move?
AUTO
MENU
SYNC
A/C

Condition Check



Damage Photos

1: Wheel osf
Scratched
Up To 50mm

2: Wing osf
Chipped
1 To 5

3: Door osf
Chipped
Edge Chip

4: Wheel osr
Scratched
Over 50mm

5: Wheel nsr
Scratched
Up To 50mm

6: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

7: Door nsf
Chipped
Edge Chip

8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint

9: Wheel nsf
Damaged
Replace

10: Wing nsf
Chipped
1 To 5

11: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK