46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LF69XNM

Mini Hatchback 1.5 Cooper Sport II 3dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	11/09/2019	**Body Style**	Hatchback	**MOT Due**	10/09/2026
Year	2019	**Keys**	2	**Gearbox**	MANUAL
Mileage	105,580 Miles Warranted	**Service history**	Yes	**Gears**	6
		Number of stamps	8	**Doors**	3
Fuel Type	Petrol	**Last service date**	18/10/2022		
Colour	RED	**Last service miles**	51,179		
VIN	WMWXR320902L60632				

£100 additional fee

Tyres

NSF	FIRESTONE	5.0mm
NSR	HANKOOK	5.0mm
OSF	FIRESTONE	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos

LF69 XNN

MINI
MINI

105580
1482.7

MODE
AUTO

AUTO
A/C

MEDIA
MENU
COM
BACK
OPTION

FM
BBC R1 15:49
You are listening to 98.8 MHz
BBC R1
BBC R1
BBC R2
ENTERTAINMENT
MODE

Condition Check



Damage Photos

1: Wheel osf
Scratched
Over 50mm

2: Door osf
Chipped
Edge Chip

3: Sill Panel Trim os
Scratched (Painted)
UpTo 25mm Thru Paint

4: Other
N/A
N/A

5: Wheel osr
Scratched
Over 50mm

6: Bumper Rear
Scratched
Over 25mm Not Thru Paint

7: Bumper Rear
Chipped
1 To 5

8: Wheel nsr
Scratched
Over 50mm

9: Door nsf
Chipped
Edge Chip

10: Door nsf
Scratched
Over 25mm Not Thru Paint

11: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint

12: Wheel nsf
Scratched
Over 50mm

13: Bumper Front
Scratched
25 to 100mm Thru Paint

14: Bonnet
Chipped
1 To 5

15: Screen Front
Cracked
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK