46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KY61HPL

Kia Sportage 1.6 GDi ISG 2 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	08/09/2011	**Body Style**	Estate	**Last service miles**	97,542
Year	2011	**Keys**	2	**MOT Due**	10/04/2026
Mileage	140,487 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Petrol	**Service documents**	Service Book	**Gears**	6
Colour	WHITE	**Number of stamps**	7		
VIN	U5YPC814LCL088306	**Last service date**	28/03/2022		

£100 ADDITIONAL FEE. Clutch replaced 29/03/2025.
Last service 28/03/2022 at 97542 miles (7 services (4 main dealer). Poor brakes
Roof will open and close very slowly need attention
Engine tapping

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Partial leather seat trim
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Central locking

Photos

GDi

INFO
SETUP CLOCK
102.40
SEEK TRACK
SCAN
AST
PTY FOLDER
A/C

303

Condition Check



Damage Photos

1: Bonnet
Poor Previous Repair
Poor Paint

2: Bumper Front
Poor Previous Repair
Poor Paint

3: Wheel nsf
Scratched
Over 50mm

4: Wing nsf
Chipped
1 To 5

No Image

5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Rusted
Over 5mm

7: Door nsr
Dented
Over 30mm

8: Qtr Panel nsr
Chipped
1 To 5

9: Wheel nsr
Scratched
Up To 50mm

10: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

11: Bumper Rear
Scratched
Over 25mm Not Thru Paint

12: Boot Lid
Poor Previous Repair
Poor Paint

13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

No Image

14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

15: Wheel osr
Scratched
Over 50mm

16: Door osr
Dented
Over 30mm

17: Door osf
Dented
Over 30mm

18: Wing osf
Poor Previous Repair
Poor Paint

19: Wheel osf
Scratched
Over 50mm

20: Screen Front
Chipped
UpTo 10mm

21: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	Fault