46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

RE16VXN

Volkswagen Sharan 1.4 TSI BlueMotion Tech S 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	13/06/2016	**Body Style**	MPV	**Last service miles**	149,240
Year	2016	**Keys**	2	**MOT Due**	21/08/2026
Mileage	155,126 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Petrol	**Service documents**	Service Book	**Gears**	6
Colour	GREY	**Number of stamps**	8		
VIN	WVWZZZ7NZGV240604	**Last service date**	22/08/2025		

Last service 22/08/2025 at 149240 miles (8 services (5 main dealer). Heater blowers noisy
Touch screen on radio does not work

Tyres

NSF	BUDGET	6.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Bluetooth connection
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Steel wheels
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos

RE16 VXN

Grt Hits Rod 80s
LO
LO


Condition Check



Damage Photos

1: Lamp osr
Broken
Replace

2: Bonnet
Chipped
Multiple Chips

3: Bumper Front
Chipped
Multiple Chips

4: Wing nsf
Scratched
UpTo 25mm Thru Paint

5: Door nsf
Dented
Between 10mm + 30mm

6: Door nsf
Scratched
Over 25mm Thru Paint

7: Door nsr
Scratched
UpTo 25mm Thru Paint

8: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

9: Bumper Rear
Cracked
UpTo 25mm

10: Tailgate
Dented
With Paint Damage

11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

12: Door osr
Dented
Between 10mm + 30mm

13: Door osr
Scratched
Over 25mm Thru Paint

14: Door osf
Scratched
Over 25mm Thru Paint

15: Wing osf
Scratched
UpTo 25mm Thru Paint

16: B Post os
Dented
Between 10mm + 30mm

17: Roof
Scratched
Rusted

18: Sunvisor ns
Broken
Replace

19: Fascia Trim
Damaged
Replace

20: Fascia Trim
Damaged
Replace

21: Screen Front
Cracked
Replace

22: Roof
Dented
Over 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK