46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**BK13JXN**

## Honda Civic 1.8 i-VTEC EX 5dr

nama GRADE 5

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 30/04/2013 | **Body Style** | Hatchback | **Last service miles** | 106,040 |
| **Year** | 2013 | **Keys** | 2 | **MOT Due** | 23/11/2026 |
| **Mileage** | 124,984 Miles Warranted | **Service history** | Yes | **Gearbox** | MANUAL |
| **Fuel Type** | Petrol | **Service documents** | Service Book | **Gears** | 6 |
| **Colour** | WHITE | **Number of stamps** | 10 | **Doors** | 5 |
| **VIN** | SHHFK2780DU003368 | **Last service date** | 15/11/2023 | | |

Last Service -15.11.2023 at 106040 miles (10 main dealer services)

### Tyres

| | | |
|---|---|---|
| **NSF** | KUMHO | 5.0mm |
| **NSR** | ROADSTONE | 5.0mm |
| **OSF** | NEXEN | 5.0mm |
| **OSR** | ROADSTONE | 5.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Central locking

## Photos

BK13 WXN

Premium Audio System
FM2
BBC R2
A/C
AUTO
SYNC

Premium Audio System
A/C
AUTO
SYNC

FM2
BBC R2
10:01

SOURCE
TA
AUDIO
SEEK SKIP
MAP
MENU
INFO
ZOOM CAT
PUSH ENTER
A/C
AUTO

## Condition Check




## Damage Photos

1: Seat Base Cover osf
Scuffed
Over 25mm

2: Bonnet
Chipped
Multiple Chips

3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing nsf
Dented
With Paint Damage

5: Bumper Front
Insecure
Action Required

6: Wheel nsf
Corroded
Light

7: A Post ns
Scratched
Over 25mm Thru Paint

8: Door nsf
Scratched
Over 25mm Thru Paint

9: Door nsr
Dented
With Paint Damage

10: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm

11: Wheel nsr
Corroded
Light

12: Qtr Panel nsr
Chipped
1 To 5

13: Bumper Rear
Scratched
25 to 100mm Thru Paint

14: Qtr Panel osr
Dented
With Paint Damage

15: Wheel osr
Corroded
Light

16: Door osr
Dented
Between 10mm + 30mm

17: Aperture Seal osr
Broken
Replace

18: Door osr
Scratched
Over 25mm Thru Paint

19: Roof
Scratched
Rusted

20: Door osf
Scratched
Over 25mm Thru Paint

21: Wheel osf
Corroded
Light

22: Wing osf
Chipped
1 To 5

23: A Post os
Scratched
Over 25mm Thru Paint

24: Roof
Dented
Over 30mm

25: Switches And Controls
Broken
Replace

26: Carpets Front
Scuffed
Over 25mm

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**

**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**

**Additional fees may apply to some vendors.**

**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |

| | | | |
|---|---|---|---|
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |