46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

VX69SHZ

Porsche Macan S 5dr PDK

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/09/2019	**Body Style**	Estate	**Last service miles**	17,568
Year	2019	**Keys**	2	**MOT Due**	15/12/2026
Mileage	39,205 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	Petrol	**Service documents**	Service Book	**Gears**	7
Colour	GREY	**Number of stamps**	2		
VIN	WP1ZZZ95ZLLB33303	**Last service date**	25/09/2023		

£90 ADDITIONAL FEE
Last Service - 25.09.2023 at 17568 miles (2 main dealer services) Front windscreen cracked

Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Front parking sensor
- PAS
- Telephone
- Air conditioning
- Folding rear seats
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Front armrest
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Remote central locking
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Traction control
- Leather seat trim
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos

NB5 SHZ

Fasten
seat belt

Heart 00s
Pop Music
Now on Heart 00s Colbie Caillat with Bubbly


REAR
FRONT
REAR
SIDE
TOP
MEDIA
PHONE
APPS
CAR
NAV

FRONT
FRONT
REAR
SIDE
TOP
MEDIA
PHONE
APPS
CAR
NAV

Condition Check



Damage Photos

1: Bonnet
Chipped
1 To 5

2: Bumper Front
Scratched
UpTo 25mm Thru Paint

3: Door nsf
Scratched
UpTo 25mm Thru Paint

4: Bumper Rear
Scratched
Up To 25mm Thru Paint

5: Bumper Rear
Scratched
25 to 100mm Thru Paint

6: Tailgate
Scratched
UpTo 25mm Thru Paint

7: Qtr Panel osr
Scratched
Over 25mm Thru Paint

8: Door osr
Scratched
UpTo 25mm Not Thru Paint

9: Door osf
Scratched
UpTo 25mm Thru Paint

10: Wing osf
Scratched
UpTo 25mm Thru Paint

11: Door osr
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK