46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BK62OYY

Seat Alhambra 2.0 TDI CR Ecomotive SE 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/10/2012	**Body Style**	MPV	**Last service miles**	130,509
Year	2012	**Keys**	2	**MOT Due**	23/06/2026
Mileage	130,784 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Diesel	**Service documents**	Service Book	**Gears**	6
Colour	BLACK	**Number of stamps**	10		
VIN	VSSZZZ7NZDV504817	**Last service date**	10/02/2026		

£90 ADDITIONAL FEE.
Clutch replaced 03/04/2025 at 119629 miles.
Last service 10/02/2026 at 130509 miles (10 services (1 main dealer). Book & print. Turbo whining

Tyres

NSF	BUDGET	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Full size spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Towbar
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos

BK62 OYY

16:45
No paired phone found
Connect
New user
130784

88.3 MHz
22.0
AUTO
REAR
REST
A/C

RADIO
MEDIA
PHONE
TIM
TP
SETUP
Look! Safe to move?
22.0
AUTO
REAR
SYNC
REST
A/C

Condition Check



Damage Photos

1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint

3: Wing nsf
Scratched
Over 25mm Thru Paint

4: Wheel nsf
Scratched
Over 50mm

5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

6: A Post ns
Chipped
1 To 5



7: Door nsf
Dented
With Paint Damage

8: Door nsr
Scratched
Over 25mm Thru Paint

9: Wheel nsr
Scratched
Over 50mm

10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

11: Bumper Rear
Poor Previous Repair
Paint Flake

12: Tailgate
Rusted
Over 5mm

13: Lamp osr
Broken
Replace

14: Qtr Panel osr
Rusted
Over 5mm

15: Wheel osr
Scratched
Over 50mm

16: Door osr
Poor Previous Repair
Poor Paint

17: Door osf
Chipped
1 To 5

18: Wing osf
Chipped
1 To 5

19: Wheel osf
Scratched
Up To 50mm

20: A Post os
Dented
Over 2 UpTo 10mm

21: B Post ns
Dented
Between 10mm + 30mm

22: Roof
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK