46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

FD61HHW

Toyota Avensis 1.8 V-matic TR 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	05/12/2011	**Body Style**	Estate	**Last service miles**	131,695
Year	2011	**Keys**	2	**MOT Due**	05/12/2026
Mileage	139,566 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	Petrol	**Service documents**	Service Book	**Gears**	6
Colour	SILVER	**Number of stamps**	14		
VIN	SB1EG76L40E066540	**Last service date**	20/06/2025		

Last Service - 20.6.2025 at 131695 miles (14 services)

Tyres

NSF	PIRELLI	6.0mm
NSR	PIRELLI	6.0mm
OSF	PIRELLI	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos

FD51 HHW

Check surroundings for safety.
23.5
23.5
AUTO

NAV
Brampton Road
Options
23.5
23.5
AUTO

Condition Check



Damage Photos

1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Dented
With Paint Damage

3: Wheel nsf
Scratched
Over 50mm

4: Wing nsf
Scratched
Over 25mm Thru Paint

5: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint

6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint

8: Wheel nsr
Scratched
Over 50mm

9: Qtr Panel nsr
Dented
With Paint Damage

10: Bumper Rear
Dented
With Paint Damage

11: Tailgate
Chipped
1 To 5

12: Qtr Panel osr
Dented
Between 10mm + 30mm

13: Qtr Panel osr
Scratched
Over 25mm Thru Paint

14: Wheel osr
Scratched
Over 50mm

15: Door osr
Scratched
Over 25mm Thru Paint

16: Door osf
Scratched
Over 25mm Thru Paint

17: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

18: Wing osf
Chipped
Multiple Chips

19: Wheel osf
Scratched
Over 50mm



20: Screen Front
Chipped
UpTo 10mm

21: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK